



विता से मुक्ति

कर्मचारी राज्य बीमा निगम अस्पताल, पीन्या  
EMPLOYEES' STATE INSURANCE CORPORATION HOSPITAL PEENYA  
(श्रम एवं रोजगार मंत्रालय, भारत सरकार के अधीन) (Under Ministry of Labour & Employment, Govt. of India)  
सर्वे सं.11-55-1, प्लॉट सं.1, 5वां मेन रोड (एफ.टी.आई. कैम्पस), यशवंतपुर सबर्ब,  
Survey No. 11-55-1, Plot No. 1, 5<sup>th</sup> Main Road (FTI Campus), Yeshwanthapur Suburb,  
यशवंतपुर पो.ऑ. बेंगलुरु-560 022. /Yeshwanthapur P.O., BENGALURU-560 022.  
फोन Ph.No.080-2357 9467 ईमेल e-mail:ms-peenya.ka@esic.in

No.492/W/17/18/2017-18-CCTV

03.01.2019

Minutes of Meeting of Pre-bid consultation in r/o E-Tender No.492/W/17/18/2017-18-CCTV dated 28.11.2018 held at ESIC Hospital, Peenya, Bangalore – 560 022.

Sl. No	Reference	Query from the bidder	Clarification from the Committee
1	Page 13, Annexure-A, BOQ sl.no.1&2.	Whether the bidder has to quote for the cameras only among the companies indicated in BOQ or other manufacturers also?	The bidder has to quote only among the companies indicated in BOQ.
2	Page 13, Annexure-A, BOQ sl.no.4	The IVMS Client Software indicated is compatible only with Sony company. This software may not be compatible with other camera manufacturers indicated?	The IVMS Client Software shall be read as 'Client Software'.
3	Page 13, Annexure-A, BOQ sl.no.10	Whether there should be dedicated slot for 2GB Graphics card indicated for computer system and make of Graphics card?	Yes 2 GB Graphics card to be a dedicated slot and make nvidia.
4	Page 13, Annexure-A, BOQ sl.no.10	Core i7 6 <sup>th</sup> Gen is indicated under Computer system configuration. Whether it should be the same since latest Generations are available?	Core i7 6 <sup>th</sup> Gen shall be read as 'latest Generation'
5	Page 13, Annexure-A, BOQ sl.no.1&2	The camera is shown as dome/bullet in r/o sl.no.1 & 2. Please specify exact quantity of Dome and bullet cameras required under 2 MP and 4 MP?	Dome Camera – 2 MP – 09 nos. Bullet Camera – 2 MP – 19 nos. Total – 2MP – 28 nos. in r/o sl.no.1 Bullet Camera – 4 MP – 12 nos. in r/o sl.no.2

Sd/-  
Medical Superintendent